From: "Guggenberger, Joe D." < guggenbergerjd@cdmsmith.com>

To: "Zhen, Davis" <Zhen.Davis@epa.gov>

"Sheldrake, Sean" <sheldrake.sean@epa.gov>

CC: younghs@cdmsmith.com

"Scott Coffey" <coffeyse@cdmsmith.com>

Date: 9/8/2018 3:19:19 PM

Subject: Fish Tissue Sampling - 9/8/18

Attachments: 100_0443.jpg

100_0445.jpg 100_0451.jpg 100_0455.jpg 100_0458.jpg

Hi Sean and Davis,

We completed fish tissue sampling. We caught four fish at six locations today, that were all attempted for the third time. We caught fish at SMB-071 (RM 9.2W), SMB-082 (RM 10.65 E), SMB-102 (RM 13.4 E), and SMB-113 (RM-15.6). We attempted fishing at SMB-080 and SMB-110 but were unsuccessful. Please see the attached photos for details.

Photo 1: Traveling under dock to fishing location for SMB-071

Photo 2: Measuring fish SMB-071.

Photo 3: SMB-082

Photo 4: SMB-102 (Note lesions near mouth) Photo 5: SMB-113 (Note lesions near tail)

Please let me know if you have any questions.

Sincerely,

Joe Guggenberger, PhD, PE
Environmental Engineer
CDM Smith
9200 Ward Parkway, Suite 320, Kansas City, MO 64114
O: 816.412.3116
C: 573.760.6565
cdmsmith.comhttp://www.cdmsmith.com/>

[http://www.cdmsmith.com/-/media/Images/CDMSmith_logo_302x180.png]https://www.cdmsmith.com/-/media/Images/CDMSmith_logo_302x180.png]

[http://www.cdmsmith.com/-/media/lcons/Social-lcons/facebook-icon-gray.png]<https://www.facebook.com/CDMSmith/> [http://www.cdmsmith.com/-/media/lcons/Social-lcons/twitter-icon-gray.png] <https://twitter.com/CDMSmith> [http://www.cdmsmith.com/-/media/lcons/Social-lcons/instagram-icon-gray.png] <https://www.instagram.com/cdmsmith/?hl=en> [http://www.cdmsmith.com/-/media/lcons/Social-lcons/linkedin-icon-gray.png] <https://www.linkedin.com/company/cdmsmith/> [http://www.cdmsmith.com/-/media/lcons/Social-lcons/youtube-icon-gray.png] <https://www.youtube.com/user/CDMSmith>